

## intelliGen Ship Loose or Service Parts

Description of Ship loose/Service Part	Part Number	List Price
Transducer Replacement Kit	28911202	\$238.00
Temperature Sensor Kit - White Leads*	89904903	\$51.00
Pressure Transducer Harness	22515102	\$164.00
EXV Replacement Kit		
E2V11BWAE0 - 3/8" x 3/8" Conn	29326101	\$818.00
E2V24BWAE0 - 3/8" x 3/8" Conn	29326201	\$818.00
E2V24BSME0 - 5/8" X 5/8" Conn	29326401	\$818.00
E3V45BSME0 - 7/8" X 1 3/8" Conn	29326501	\$1,609.00
E2V11BWAE0 - 7/8" X 1 3/8" Conn	29326601	\$1,609.00
Expansion Valve molded connector - 40" Conn (Bipolar Valves)	22592101	\$149.00
Transformers		
120/24 volt - 40 VA	22529601	\$75.00
240/24 volt - 40 VA	22529602	\$76.00
460/24 - 40 VA	22529603	\$93.00
600/24 - 40 VA	22529701	\$128.00
iRC Replacement Kit	28918001S	\$828.00
iRC-UI Replacement Kit	28918201S	\$538.00
iWC Replacement Kit	28918301S	\$719.00
Door Switch Kit (includes door switch and cables) Ship Loose kit	22543101	\$83.00
iIC Replacement Kit	28918401S	\$409.00
Cable Ribbon. iRC-UI to iRC Center Mount Unit Cooler 8" Replacement Kit	22602101	\$104.00
Cable Ribbon. iRC-UI to iRC - Low Profile Unit Cooler 14" Replacement Kit	22602102	\$207.00
Cable Ribbon. iRC-UI to iRC - Large Unit Cooler 35" Replacement Kit	22602103	\$311.00
Cable Ribbon. iRC-UI to iRC- Medium Profile and Large Unit Cooler 24" Replacement Kit	22602104	\$414.00
EV-COM Cable- Large Unit Cooler DUAL iRC Board Replacement Kit	22596801	\$518.00

\*Only the sensor with white leads is shipped as a service replacement part